


2A152



Rocky Mountain
Remediation Services, L.L.C.
... protecting the environment

INTERNAL CORRESPONDENCE



000059253

DATE: October 11, 1995

TO: A. D. Muniz, Finance & Administration, Building T891E, X6041

FROM: *JRC* J. R. Cirillo, RMRS Environmental Remediation Projects, Bldg. T891B, X5876

SUBJECT: BUILDING 891, OPERABLE UNIT 2 FIELD TREATABILITY UNIT AND MAIN
AND "PA" DECON PADS WINTER ASSESSMENT - JRC-012-95

Action: No action

The post winter assessment for Building 891, Operable Unit 2 Field Treatability Unit and Main and PA Decon Pads have been completed in accordance with 4-74100-ADM-025. No freeze related occurrences or failures occurred during winter 94/95, therefore, no engineering evaluations are required in this facility. No corrective actions related to freeze protection remain open in the facility.

If you have any questions or require additional information, please do not hesitate to give me a call on extension 5876 or digital page 4011.

kld

cc:

M. C. Broussard - T893B
M. T. Vess *mtv* - T891B
ER Records Center (2) 080



ADMIN RECCRD

IA-A-000696

1/1